

## Unacceptable Warranty

Airtex products returned for warranty consideration exhibiting the following will not be reimbursed and will be coded accordingly.

### R Code Reason

100	Not submitted in Airtex replacement unit box
101	Part received does not match part number on Claim Form
102	New, parts missing
103	Original strainer not returned with pump
104	Miss-applied by customer
105	Modified by customer
106	New, never Installed
107	Not supplied by Airtex
200	Damage attributable to vehicle electrical/connector fault
201	Physically damaged
202	New, parts broken
203	Damaged during installation
204	Fuel contamination (dirt, rust, etc.)
205	Plugged or contaminated strainer
206	Rusty or corroded
207	Shipping damage
208	Normal wear and tear
300	Claim Form submitted without part
301	Part submitted without Claim Form
302	Claim Form is incomplete
400	Other: _____

Airtex will retain products coded above for 45 days after which they will be scrapped. R coded product can be returned to the sender freight collect, if so requested, prior to the 45 day Scrap Date.